



Legend:

► X	shut off armature	TI	temperature indicator	► X	overflow valve	PT	pressure sensor	► X	electric actuated valve	PZA	safety pressure switch	► X	foot operated purge valve	FS	flow control switch	□	shut off flap	►	ignite-gas-burner
► X	ball valve	PI	pressure indicator	► X	pressure reducing valve	TS	thermostate	► X	3 way electric actuated valve	TA	safety temperature sensor	► X	pressure regulated valve	LI	reflex level gauge	□ D	pneumatic flap	►	proval burner
► X	regulating valve	TT	temperatur transmitter	► X	recirculation valve	PS	pressure switch	► X	solenoid valve	QC	conductivity control	► T	strainer	LS	level switch	LZA-	water insufficiency control	○	orifice
► X	3 way valve	TC	temperatur control	► X	safety valve	TZA	safety thermostate	► X	pneumatic actuated valve	FIQ	flow indicator with counter	► □	non return flap	LC	continuous level control	LZA+	overfill control	D	reduction
●	Burner	○	on-site indication	○	control room indication	○	control SPS	□	flue gas compens.	●	pump	●	fan	○	gauge glass	○	condensate trap	■	filter
—	water level indicator	—	blind flange	—	border of delivery	—	—	—	—	—	—	—	—	—	—	—	—	—	

Hydr.	Verbindungshinweis / Notice / Nota / Remarque: »	P&I diagram steam boiler plant with additional equipment	Hoval	
		Achtung! Für die Installation muss das anlagenbezogene Schema verwendet werden! Attention! This is just a schematic. For installation please use the detail-plan! Attenzione! Per la messa in opera, utilizzare le schema dettagliato! Attention! Pour la réalisation pratique de l'installation, il faut utiliser le schéma détaillé!		
1			Datum Name 17.01.2012 ...	
			Version	
			Datei: ...	